


Freestanding Bath / Shower Mixer

Instruction Guide

Service Parts



Helpful Tools



SCREWDRIVER



ADJUSTABLE WRENCH



FLASHLIGHT




SAFETY GLASSES


No	Product Description	QTY
1	Control body	1
2	Body Pipe	1
3	Panel	1
4	Water pipe	2
5	N-box	1
6	Expansion Screw	4
7	Hand shower	1
8	Shower hose	1
9	Instruction	1
10	Screw tool	1

Installation Method


Notice: The minimum floor depth required is 50 mm. When the floor depth undersized, and extra concrete block of 30 mm is needed.




1. Drill the hole on the floor to fit the N-box; Pay special attention to the distance between Bathtub and N-box.



2. Adjust the level by gradiometer. Fix by M6 expansion screw.




3. Jointing hot and cold water joints. Ensure no leakage.




Installation Method


4. Take special protection of N-box when doing the tile work.




5. Take out spare parts, cover, test parts and gradiometer.



6. Connect body by H8 screw tool.




7. Fix panel by M4 screw.




IGMX0301(2019/10)

Installation Method


8. Connect control body and pipe.




9. Fix pipe in N-box, adjust position, fix panel by M5 screw.



10. Fix shower hose and hand shower.



11. Installation finished.



IGMX0301(2019/10)

Maintenance Method



Cleaning the finish with Caution in oroef to avoid any damage and preserve the original beauty.



Cleaning the surface Of any finish wity water and mild soap. Dry with a soft Cloth.



Periodical Cleaning should be made in order to keep the Outlook always shiny.



Never use rough sponges. abrasiver or chemical cleaners that contains acides or harsh solvents.

IGMX0301(2019/10)